



DATE 11/12/81

SSC Service Bulletin

no. 81-220

TO: ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES & SERVICE CENTERS
ALL REGENCY COMMUNICATIONS PROFESSIONAL SALES REPRESENTATIVES

MODELS AFFECTED: XLU SERIES

PROBLEM: WHEN INTERFACING THE MA-330 OR MA-331 WITH THE XLU SERIES RADIOS, THE AUTOMATIC PTT CIRCUIT FOR THE TOUCH PAD WILL NOT ENGAGE THE TRANSMITTER

CURE:

Add a 22K ohm resistor (4704-0223-032) from the base of Q602 to ground on foil side of P.C. Board.

TECHNICAL SERVICE DEPARTMENT
REGENCY COMMUNICATIONS, INC.



